

Electrical Product Safety Recall

**Output Connector Clamps of Projecta Battery Chargers
Models: AC008, AC015, AC040, AC080, SMC150, SMC400, SMC800**



The recall covers the output connector clamp of the Projecta battery chargers which were sold at hardware and automotive parts retailers between 2017 and 2022. Only Models AC008, AC015, AC040, AC080, SMC150, SMC400, SMC800 are affected.

The output connector clamps that have a visible engraved 'Vo' or yellow paint dot, are not part of this recall.

Defect: The plastic covers on the output connector clamps are not adequately resistant to fire. They may overheat and catch fire.

Hazard: Risk of fire or burns causing serious injury.

What to do: Stop using the affected output connector clamps immediately.

- Please visit the website <https://www.projecta.com.au/technical-support/component-replacement-campaign> for further information and to register your details to receive replacement clamps.
- Alternatively, please scan the following QR code for details.



Contact Details Consumers can contact Brown and Watson International by email at componentreplacement0123@brownwatson.com.au or by phone on 1800 154 444 (TOLL FREE).

See www.productsafety.gov.au for Australian product recall information