



Product Safety Recall



Do you own this product?

MAP Automotive Key Fob Shells

Dates sold: 22 June 2022 – 26 September 2023



Why the product is recalled: The product does not comply with the mandatory safety standard for products containing button/coin batteries. The button/coin battery compartment is not adequately secured and can be accessible to young children.

Hazard: There is a risk of choking, severe internal burn injuries or death to young children if they gain access to the button/coin batteries and swallow or place them inside their body. Severe or fatal injuries can happen in 2 hours or less.



1. Consumers should stop using the product immediately.
2. Consumers should contact Innovative Mechatronics Group or the retailer the product was purchased from for a full refund.



Ask our staff to find out more about the recall.

sales@maparts.com.au

03 8792 6999 9am to 5pm Monday to Friday



Purchased from: Repco, Supercheap Auto, Bapcor, Veales, Wesfil, Autobarn, Auto 1



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2023/19959

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information